

WO #: PE9917

WO Desc: change manuel M1 valve

Parent WO#:

WO Long Desc: valve on reactor has nuts on valve to tight packing these must be vibrating loose.valve should be marked not forM1

WO Priority: 2

Location: E-R-15

REACTOR 15

Asset: 1347819

REACTOR 15

Asset Service:

Entry Date: 1/5/2009

WO Status: CLOSE

Action Code: LDAR

Project #:

Originator: Anthony Bernardini

Status Date: 7/6/2009

Work Type: CM

Failure Class: VSSL

Job Plan:

Planned Start:

Actual Start: 1/6/2009

Review Date:

PM/Bundle:

Planned Completion:

Actual Completion: 1/6/2009

Plant Information

RC: PERC01

Planner: WILLIAM STONEKING

MOC#:

When Code: RT

Lead Craft: MECH

MOC Status:

P&ID:

MOC Desc:

SIR/EIS Required:

Work Order Notes

JOSEPH VITTONI

01/06/2009 Tightened packing on valve.

Completed by Emp #: _____

Signature: _____